

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T 49 NR 10-11 W

\_\_\_\_\_ Luce \_\_\_\_\_ COUNTY

DESCRIPTION OF CORNER Section Corner common to Sec.'s 30-31-36-25

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

12" Jackpine	S 3° W	7 links
	"S 36 NBT"	
11" Jackpine	N 8° W	77½ links
	"S 25 NBT"	
11" Red Pine	S 84° E	125½ links
	"S 31 NBT"	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced section corner as set by Marcus Schaff, Reg. Surveyor.

Found 2" pipe in concrete.

No evidence of original witnesses.

Section corner lies in line with fire lane to east and 20 links south of fire lane from west.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 6/25/57  
REGISTERED LAND SURVEYOR