

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. ~~48-49~~ NR. 11 W. . . .

Luce

COUNTY

DESCRIPTION OF CORNER Section Corner common to Sec.'s 1-2-35-36

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 6" W. Pine N 59° W 73 links

"S 35 NBT"

9" W. Pine S 18° W 24 links

"S 2 NBT"

9" W. Pine N 45° E 29 links

"S 36 NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced corner as set by Marcus Schaff, Reg. Surveyor.

Found 2" iron pipe in concrete.

Found remains of two hemlock B.T.s bearing N 59° E 43 links and N 20° W 40 links, both stumps in poor condition.

SURVEYORS SEAL

SIGNED

Billy D. Buckles
REGISTERED LAND SURVEYOR

DATE 6/25/57