

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR 11 N.

----- Luce ----- COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 29-30 -----

DESCRIPTION OF CORNER MONUMENT 2" Iron Pipe in N-S Firelane -----

WITNESSES TO CORNER 6" Jackpine (1/4 S. NBT) - S 69° E - 35 Links -----

5" Jackpine (1/4 S. NBT) - N 38° E - 35 1/2 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed Corner as set by Marcus Schaaf, Reg. Surveyor.

Found 2" Iron Pipe in place with Yellow Pine B.T. Bearing N 62° W 9 Links.

Corner lies in N-S Firelane.

Shown by J. Kutchera and L. Rubick.

Corner was re-witnessed June 17, 1958.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 12/3/58