MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_49_ NR_11 U__

LinceCOUNT
DESCRIPTION OF CORNER 1/4 Corner between Sections 20-29
DESCRIPTION OF CORNER MONUMENT_1" Pipe with 4"_Brass Cap
WITNESSES TO CORNER _ 12" Unite_Pine (1/48-18T) -S-490 W-18-1-18-1-1-1
13" Med Pine (1/45 NDT) _ N 390 // 30 Tinks

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Corner as set by Marcus Schaaf, Reg. Surveyor.

Found 2" Iron Pipe in Place.

Stp. E 3 Links. Poor Condition.

Corner lies in E-W Firelane.

Corner placed and witnessed June 17, 1958.

SURVEYORS SEAL

GNED _ _ Billy D. Buckle

ISTERED LAND SURVEYOR

DATE _12/3/58_