

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49N N.R. 11W


Luce COUNTY

DESCRIPTION OF CORNER ¼ Cor. bet. Secs. 9-10

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8-11-70

WITNESSES TO CORNER..... 9" Cedar (½S NBT) S50°W 43.9'



17" W. Pine (½S NBT) S30°E 21.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at a 2" iron pipe, set by Marcus Schaaf, R.L.S.
Corner lies in a firelane clearing to north.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler, DATE 8-21-70
REGISTERED LAND SURVEYOR