

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION



# LAND CORNER RECORD

T. 49N N.R. 11W


Luce COUNTY

DESCRIPTION OF CORNER ± Cor. bet. Secs. 19-20

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8-24-70

WITNESSES TO CORNER..... 8" J. Pine (±S NBT) S86°E 15.6'



8" J. Pine (±S NBT) S36°W 16.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from one W. Pine stump, a possible B.T., bearing, N40°W, 29 links.

Cor. lies in intersection of firelanes, to north, south and west.

Found 2" iron pipe at the W. Pine witness, apparently removed by traffic.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*  
Billy D. Buckler DATE 8-31-70  
REGISTERED LAND SURVEYOR