

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 49N N.R. 11W


Luce COUNTY

DESCRIPTION OF CORNER West 1/16 Cor. bet. Secs. 25-36

CORNER MONUMENT 1 1/2" IRON PIPE

DATE MONUMENT PLACED AND WITNESSED 8-28-70

WITNESSES TO CORNER..... 9" Red Pine (W 1/16 B.T.) S81°W 22.0'



8" Jack Pine (W 1/16 B.T.) S22°E 8.9'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as set by Marcus Schaaf, R.L.S.
Corner lies 18' south of a fire lane intersection from North, East and West.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 9-22-70
REGISTERED LAND SURVEYOR