

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 49N N. R. 11W


Luce COUNTY

DESCRIPTION OF CORNER East 1/16 Cor. bet. Secs. 25-36

CORNER MONUMENT 1 1/2" iron pipe

DATE MONUMENT PLACED AND WITNESSED 8-28-70

WITNESSES TO CORNER..... 8" Red Pine (E 1/16 B.T.) N83°W 26.5'



5" Jack Pine (E 1/16 B.T.) S7°W 16.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as set by Marcus Schaaf, R.L.S.

Corner lies 15' south of an East-west fire lane.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 9-22-70
REGISTERED LAND SURVEYOR