

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 49N N.R. 11-12W


Luce COUNTY

DESCRIPTION OF CORNER North 1/16 Cor. bet. Secs. 19-24

CORNER MONUMENT 1 1/2" iron pipe, buried in center of N-S firelane

DATE MONUMENT PLACED AND WITNESSED 8-27-70

WITNESSES TO CORNER..... 8" Red Pine (N 1/16 BT) S12°E 30.2'



6" Red Pine (N 1/16 BT) N65°W 19.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as set by Marcus Schaaf, R.L.S.
Found iron pipe, bent over from vehicle traffic. Drove pipe below road level.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 8-31-70
REGISTERED LAND SURVEYOR