

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Luce COUNTY


T 49N R 11W

DESCRIPTION OF CORNER 1/4 Cor. bet. Secs. 13-14

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 7/16/71

WITNESSES TO CORNER..... 14" W. Pine (1/4 S NBT) S13°E 26.3'



15" W. Pine (1/4 S NBT) N86°W 30.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.
This corner placed midway bet. two Sec. Cors. and in center of N-S firelane.

Found no evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 12/17/71
REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓

R 4047
Rev. 10/68