

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Luce COUNTY
T 49N R 11W

DESCRIPTION OF CORNER 1/4 Cor. bet. Secs. 23-24

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 7/17/71

WITNESSES TO CORNER..... 9" Red Pine (1/4 S NBT) S54°W 74.8'



6" W. Pine (1/4 S NBT) S47°E 50.9'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This 1/4 Cor. re-established midway and on line bet. two Sec. Cors. Sec. 24 was sub-divided by Marcus Schaaf, R.I.S. Monument was removed during construction of the Grand Marias road.

Corner lies in intersection of the N-S firelane and the E-W road.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE

12-17-71

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓

R 4047
Rev. 10/68