

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Luce COUNTY


T 49N R 11W

DESCRIPTION OF CORNER North 1/16 Corner bet. Secs. 23-24

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 7/17/71

WITNESSES TO CORNER..... 7" R. Pine (N 1/16 BT) S42°E 26.7'



8" R. Pine (N 1/16 BT) N27°E 29.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.
This corner placed midway and on line bet. Sec. Cor. to north and $\frac{1}{4}$ Cor. to south.
Corner is on west edge of N-S firelane and in line with firelane to east.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE

12/17/71

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓

R 4047
Rev. 10/68