

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 48-49 NR. 11. W. . .

----- Luce ----- COUNTY

DESCRIPTION OF CORNER Section corner between Sections 5, 6, 31 and 32. . .

DESCRIPTION OF CORNER MONUMENT Department Marker. . .

WITNESSES TO CORNER .13" W. Pine . N 46 W . 46 Links (S 31 NBT) . . .

.15" W. Pine . S 7 E . 31 Links (S 5 NBT) . . .

.12" W. Pine . N 40 E . 57 $\frac{1}{2}$ Links (S 32 NBT) . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was replaced as set by Marcus Schaaf, in intersection of firelanes N-E.

Found 2" Iron Pipe in place.

Recent bulldozing in area has removed original witnesses.

Shown by McTiver, District Forester.

Corner was placed and witnessed on 10 June 1958.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 5-29-59
REGISTERED LAND SURVEYOR