

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 11 - 12 W

Luce COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 13 and 18.

DESCRIPTION OF CORNER MONUMENT 2" Iron Pipe for monument.

WITNESSES TO CORNER 16" Hemlock N 53 E 49 Links (1/4 S NE)

13" W. Pine S 55 W 112 Links (1/4 S NW)

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was re-witnessed as set by Marcus Schaaf, Reg. Surveyor. Found
2" Iron Pipe in place. No evidence of Beech or Maple witnesses.

1/4 corner lies in N-S firelane.

Corner was placed and witnessed on 10 June 1958.

SURVEYORS SEAL

SIGNED Billy D. Buckler
REGISTERED LAND SURVEYOR DATE 5-29-59