FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co.

1 Corner.

FOR CORNERS OF -:	LOCATED IN -:		CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T. <u>49 \$</u> , R. <u>11</u>	- X .		
2. PROPERTY CONTROLL- ING IN SECTION—	N. S., R	E. W.		
3. M SCELLANEOUS PROPERTY IN SECTION	,T S., R	E. W.		
4, LOT NO, RE	CORDED PLAT			
5, PRIVATE CLAIMS				REGISTER OF DE

FILING NUMBER

- A. Description of original monument and accessories and/or subsequent restoration:
- G-5 Re-monumented Section Corner 9-10-15-16, set by Billy D. Buckler, R.L.S., dated 5-19-59.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-5 Re-set from one original B.T. and one N.B.T.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-5 Euried 1" x 36" iron pipe. New Eearings:

14" W. Fine, N64°W, 107.1"

6" k. Pine, SO4 E, 69.9"

6" J. Fine, S67°E, 7.0'

15" R. Pine, S78°W, 58.7'

SIGNED BY Lavid & Ballett

DATE 12-21-82

David Eabbitt SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)