

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 12 W. .

----- Luce ----- COUNTY

DESCRIPTION OF CORNER 1/4 Section Corner between Sections 16 and 17 . . .

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap . . .

WITNESSES TO CORNER 10" S. Maple . . . N 40° E . . . 21 links . . .

12" S. Maple . . . S 75° W . . . 25 links . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner from Hemlock and Yellow Birch B.T.'s in poor condition.

Corner lies near East edge of marsh.

Corner shown to us by Bernard McTiver, District Forester.

Corner placed and witnessed June 19, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buchler DATE 6/21/56
REGISTERED LAND SURVEYOR