

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 12 W. .

----- Luce ----- COUNTY

DESCRIPTION OF CORNER ~~Section Corner common to Sections 3, 4, 9, 10~~ . . .

DESCRIPTION OF CORNER MONUMENT ~~1" pipe with 4" brass cap~~ . . .

WITNESSES TO CORNER ~~15" Red Pipe~~ ~~N 45° W~~ ~~40 links~~ . . .

~~12" Red Oak~~ ~~N 70° E~~ ~~43 links~~ . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner from one Yellow Pine B.T. in place, good condition.

2" Iron Pipe with concrete bottom.

Corner lies on North edge of marsh.

Corner shown to us by Bernard McTiver, District Forester.

Corner placed and witnessed June 13, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 6/21/56
REGISTERED LAND SURVEYOR