

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 49.. NR. 12 W ..

..... Luce ..... COUNTY

DESCRIPTION OF CORNER 1/4 Section Corner between Sections 3 and 4 .....

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap .....

WITNESSES TO CORNER 14" Red Pine N 27° E 128 1/2 links .....

10" Red Pine S 60° W 111 links .....

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner from one Spruce Pine B.T. in good condition (down).

2" Pipe with concrete bottom in place; buried.

Corner lies on SE edge of trail road NE-SW.

Corner shown to us by Bernard McTiver, District Forester.

Corner placed and witnessed June 13, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 6/21/56  
REGISTERED LAND SURVEYOR