

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 12 W.

----- Luce ----- COUNTY

DESCRIPTION OF CORNER .. Section Corner common to Sections 8, 9, 16, 17 ..

DESCRIPTION OF CORNER MONUMENT ... 1" pipe with 4" brass cap

WITNESSES TO CORNER .. 6" Cedar .. N 70° E .. 33 links ..

10" Cedar .. S 45° W .. 45½ links ..

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner from one Cedar B.T. in excellent condition (green).

Corner shown to us by Bernard McTiver, District Forester.

Corner placed and witnessed June 11, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 6/11/56
REGISTERED LAND SURVEYOR