

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T..49. NR.12 W..

..... Luce COUNTY

DESCRIPTION OF CORNER .. 1/4 Section Corner between Sections 15 and 16 ..

DESCRIPTION OF CORNER MONUMENT .. 1" pipe with 4" brass cap ..

WITNESSES TO CORNER .. 12" Cedar .. S 30° W .. 51½ links ..

..... 10" Soft Maple .. S 29° E .. 50 links ..

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner from one Tamarack B.T. in good condition.

Corner lies near South edge of Spr. swp.

Corner shown to us by Bernard McTiver, District Forester.

Corner placed and witnessed June 11, 1956.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 6/13/56