

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T.49.. NR.12.W..

..... Luce COUNTY

DESCRIPTION OF CORNER .. 1/4 Corner between Sections 4 and 5 ..

DESCRIPTION OF CORNER MONUMENT .. 1" pipe with 1/4" brass cap ..

WITNESSES TO CORNER .. 10" Red Pine .. N 48° W .. 24 1/2 links ..

18" Red Pine .. N 33° E .. 64 1/2 links ..

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner from one Jack Pine B.T. in poor condition.

Corner shown to us by Bernard McTiver, District Forester.

Corner placed and witnessed June 11, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 6/13/56
REGISTERED LAND SURVEYOR