Cons. 4047
4/56

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T 49 NR 12 W

Luce COUNTY

DESCRIPTION OF CORNER Section Corner common to Sec.'s 13-14-23-24

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 12" Hemlock N 31° W 95½ links
"S 14 NBT"
12" Hemlock S 86° W 44 links
"S 23 NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced section corner as set by Marcus Schaff, Reg. Surveyor.

Found 2" ironpipe in place. Notes indicate corner was set by proportionate measure and stump holes for both beech B.T.s were found. Corner lies at intersection of fire lanes east and south.

Corner shown to us by B. McTiver, District Forester.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 6/26/57
REGISTERED LAND SURVEYOR