

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 49 NR 11-12 W

----- Luce ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sec.'s 6-7-1-12 -----

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap -----

WITNESSES TO CORNER 7" Jackpine ----- N 42° W ----- 30 links -----  
"S 1 MBT"

7" Jackpine ----- N 45° E ----- 36 links -----  
"S 6 MBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced section corner as set by Marcus Schaff, Reg. Surveyor.

Found 2" iron pipe in place. No evidence of original B.T.e.

Corner lies in intersection of fire lanes north, south and east.

Squared and scribed 3" jackpine at corner.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 6/26/57  
REGISTERED LAND SURVEYOR