

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 12 W.

Ince

COUNTY

DESCRIPTION OF CORNER Section Corner common to Sec.'s 14-15-22-23

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

<u>8" W. Pine</u>	<u>S 32° E</u>	<u>67 links</u>
	<u>"S 23 NBT"</u>	
<u>11" Hemlock</u>	<u>N 65° E</u>	<u>11 links</u>
	<u>"S 14 NBT"</u>	
<u>11" Hemlock</u>	<u>N 12° W</u>	<u>31 links</u>
	<u>"S 15 NBT"</u>	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced section corner as set by Marcus Schaff, Reg. Surveyor.

Found 2" iron pipe in place. Found remains of hemlock stump S 35° E 24 links and beech stump bottom N 8° W 20 links. Checked distance to maple line tree 10.74 chs. east. Line tree is stub, dead and rotted badly.

Placed location pester 6 chs. south on road. Placed location pester 18 chs. east on road.

Corner lies on steep hillside facing north.

Corner shown to us by B. McTiver, District Forester.

SURVEYORS SEAL

SIGNED

Billy D. Buckles
REGISTERED LAND SURVEYOR

DATE 6/26/57