

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 49N N.R. 12W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Cor. bet. Secs. 28-33

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8-20-70

WITNESSES TO CORNER..... 10" Cedar (1/4 S NBT) N12°E 13.3'



10" Cedar (1/4 S NBT) S61°E 24.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from original cedar witness tree, bearing N30°W, 35 links
Tree is still growing. Found several blazes by timber cruisers dating to 1931.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler DATE 8-26-70
REGISTERED LAND SURVEYOR