

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 49N N.R. 12W

Luce COUNTY


DESCRIPTION OF CORNER  $\frac{1}{4}$  Cor. bet. Secs. 25-26

CORNER MONUMENT 2" iron pipe, buried in N-S Firelane.

DATE MONUMENT PLACED AND WITNESSED 8-19-70

WITNESSES TO CORNER..... 7" Red Pine ( $\frac{1}{4}$ S NBT) S32°W 22.2'

6" J. Pine ( $\frac{1}{4}$ S NBT) S56°E 12.5'



AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as placed by Marcus Schaaf, R.L.S.  
Found pipe in place with remains of a W. Pine B.T., bearing S66°E, 26 links  
in poor condition.

SURVEYOR'S SEAL

*Billy D. Buckler.*  
SIGNED Billy D. Buckler DATE 8-26-70  
REGISTERED LAND SURVEYOR