

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES



LAND CORNER RECORD

Luce COUNTY


T 49N R 11-12W

DESCRIPTION OF CORNER North 1/16 Cor. bet. Secs. 12-7

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10/22/71

WITNESSES TO CORNER..... 6" Red Pine N73°E 27.3'



8" Red Pine S51°E 23.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.
Corner placed midway and on line bet. Sec. Cor. to north and $\frac{1}{4}$ Cor. to south.
Corner lies in center of N-S fireline.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 12/17/71

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓

R 4047
Rev. 10/68