

✓

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Luce COUNTY
T 49N R 12W

DESCRIPTION OF CORNER West 1/16 Cor. bet. Secs. 13-24

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9/24/71

WITNESSES TO CORNER..... 14" Hemlock S23°W 47.3'



18" Hemlock N64°E 25.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner placed midway and on line bet. Sec. Cor. to west and $\frac{1}{4}$ Cor. to east.

Corner lies on north edge of E-W fireline.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 12/17/71
REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓

R 4047
Rev. 10/68