

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Luce COUNTY  
T 49 R 12W

DESCRIPTION OF CORNER East 1/16 Cor. bet. Secs. 13-24

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9/24/71

WITNESSES TO CORNER..... 24" W. Pine S41°W 45.6'



12" R Pine N30°W 11.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies in north rut of e-w fireline/

Corner placed midway and on line bet. Sec. Cor. to east and  $\frac{1}{4}$  Cor. to west.

SURVEYOR'S SEAL

*Billy D. Buckler*

SIGNED

Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE

12/17/71

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing ✓

R 4047  
Rev. 10/68