## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

DESCRIPTION OF CORNER				Luce COUNTY
CORNER MONUMENT <u>1" pipe with 4" aluminum cap</u> DATE MONUMENT PLACED AND WITNESSED <u>6-18-71</u> WITNESSES TO CORNER <u>12" Red Pine (\$\frac{1}{4}\$\$ NBT) \$ 45^\text{OW} 27.9</u>			T <u>49</u> 2	N R 12W
DATE MONUMENT PLACED AND WITNESSED 6-18-71  WITNESSES TO CORNER 12" Red Pine (\$\frac{1}{4}\$\$ NBT) \$ 45\frac{0}{4}\$ 27.9	DESCRIPTION OF CORNER	÷ bet. Secs. 23-26		
WITNESSES TO CORNER 12" Red Pine ( S NBT) S 45°W 27.9	CORNER MONUMENT 1" p1;	pe with 4" aluminum cap		
N —	DATE MONUMENT PLACED ANI	D WITNESSED <u>6-18-71</u>		
11" W. Pine (\frac{1}{4}\$ NBT) S 380E 16.4	WITNESSES TO CORNER	<u>12" Red Pine (#s NBT)</u>	s 45°W 27.9	
V23	N23	ll" W. Pine ( $\frac{1}{4}$ s NBT) S	38 <sup>0</sup> E 16.4	
AND		AND		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner re-established midway bet. two Sec. Cors. and in center of an E-W firelane. Found no evidence of the original cor. Corner had been established by Marcus Schaaf, R.L.S. but apparently monument was removed by traffic.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Byckler

REGISTERED LAND SURVEYOR

DATE 12-7-71

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047 Rev. 10/68