

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 50. NR. & W. . . .

--- Luce --- COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 16-17

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 8" Red Pine (1/4S NBT) N 79° E 29 Links

9" Red Pine (1/4S NBT) N 22° E 33 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Corner from two White Pine B.T.s bearing N 39° E 29 Links and N 74° W 40 Links. Bottom face and notch remains on both stumps. Found wood post and Iron Pipe in place.

Corner lies one chain North of Woods Road.

Placed Location Poster one chain South of Corner on Road.

Corner placed and witnessed June 16, 1958.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 12/3/58
REGISTERED LAND SURVEYOR