

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 50N N.R. 8W


Luce COUNTY

DESCRIPTION OF CORNER ¼ Cor. bet. Secs. 19-30

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 5-4-70

WITNESSES TO CORNER..... 8" Red Pine (½S NBT) N36°E 31.1'



CIRCLE CORNER REGISTERED

10" Red Oak (½S NBT) N87°E 37.8'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from two jack pine stump bottoms, possible original witnesses. Distance checks east (75 links) to bottom of hill and west to an original Section Corner.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*  
Billy D. Buckler DATE 1-25-71  
REGISTERED LAND SURVEYOR