## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co.

4 Corners

FOR	CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER		
	BLIC LAND SURVEY		y-bec.  ,   -bec.		
2. Pi	ROPERTY CONTROLL- 11 ING IN SECTION	,T. 50 N. R. 8 W.	2-Sec.11, 15-Sec.11		
3. MISCELLANEOUS PROPERTY IN SECTION, T S., R W.					
4. LC	OT NO, RECO	RDED PLAT			
5. PF	IVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER	
I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 5-15 & 2-5, 19 80, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on, 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:					
A. Description of original monument and accessories and/or subsequent restoration: 9-Sec.11 East 1/16 Corner of Section 11.					
11-Sec.11	I-Sec.11 South-West 1/16 Corner of Section 11.				
12-Sec.11	c.11 South 1/16 Corner of Section 11.				
15-Sec.11 West 1/16 Corner on South side of Section 11.					
В. І	Description of corner evidence	e found and/or method app	lied in restoring or re-establishin	ng corner:	
	2-Sec.11 Placed corner 1,320' East of post at center of section.				
11-Sec.11	Sec.11 Placed corner 1,319.3' North of the section line and 1,310.4' West of the N-S 1/4 line.				
12-Sec.11 Placed corner midway bet. a wood post at center of section and the South 1/4 corner.					
15-Sec.11 Placed corner midway and on line bet. 1/4 cor. to East and Sec. Cor. to West.					
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  Placed 1" pipe with 4" aluminum cap at all 4 corners. Bearings:					
9-Sec.11	12" Hemlock, S70°E,	, 27.5' & 14" Spruc	s, 58°E, 35.8' & 7" S.	Maple, North, 15.7'.	
11-Sec.11	-Sec.11 20" Hemlock, S67°W, 32.6' & 4" Hemlock, N75°E, 13.0' & 12" Spruce, S45°E, 9.9'.				
12-Sec.11	-Sec.11 8" Hemlock, S62°W, 43.7' & 12" Hemlock, N78°E, 43.7' & 6" Hemlock, N38°E, 24.6'.				
15-Sec.11	12" Y. wirch, S55 w 7" Spruce, S83°E, 2	I, 28.1' & 7" S. Ma; 27.7'•	ole, N63 <sup>0</sup> W, 8.9' & 6" 5	6. Maple, N26°E, 7.9' «	
SIG	NED BY		DATE 10-9-6	NATE OF MICE	
sur	Billy D. Buckl VEYOR'S MICHIGAN REG	er 888 ISTRATION NO	7	BUCKLER S	
FOF	STATE AND UNITED ST	ATES AGENCIES:		SURVEYOR )	
SIG	NED BY	CHIEF OF SURVEY PARTY	DATE	1 AND 50	
APP	ROVED AND SIGNED BY_	MICHIGAN REGISTERED	LAND SURVEYOR	(SEAL)	
SURVEYOR'S MICHIGAN REGISTRATION NO					