

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co.

2 Corners.

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>50</u> N. <u>2</u> , R. <u>8</u> <u>W.</u>	<u>J-4</u>
2. PROPERTY CONTROLL- 11 ING IN SECTION _____	, T. <u>50</u> N. <u>2</u> , R. <u>8</u> <u>W.</u>	<u>6-Sec.11</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____	, T. _____ N. _____, R. _____ E. _____	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on _____, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

J-4 Center Corner of Section 11.

6-Sec.11 North-East 1/16 Corner of Section 11.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

J-4 Placed corner at a wood post set by H.C. Lawrence, R.L.S. Corner is 2,638.65' North of the South 1/4 corner of section 11.

6-Sec.11 Placed corner due West of a iron pipe (1,321.6'), found at the North 1/16 corner on east side of Section 11. Found a post and 4" iron pipe 22.6' North & 6.0' East of cor.


C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed 1" pipe with 4" aluminum cap at both corners. Bearings:

J-4 6" Hemlock, S52°E, 15.5'	6-Sec.11 12" Hemlock, S24°W, 22.4'
6" Spruce, N67°E, 14.2'	10" R. Maple, S30°W, 13.8'
6" Y. Birch, N5°E, 3.3'	12" R. Maple, N1°E, 44.8'

SIGNED BY Billy D. Buckler DATE 10-9-80

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887



FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____