## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co.

1 Corner

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 50 N. R. 8 W.	A-12
2. PROPERTY CONTROLL- ING IN SECTION	,T N. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	N. E. W. S., R. W.	
4. LOT NO , REC	ORDED PLAT	
5. PRIVATE CLAIMS		RE

REGISTER OF DEEDS STAMP AND

- A. Description of original monument and accessories and/or subsequent restoration:
- A-12 West 1/4 Corner of Section 31. Corner placed by Billy D. Buckler, L.S. on 2-17-59. DNR Monument. Wit: 7" W. Pine, S88°W. 16 lks. & 10" R. Pine, N47°E, 29 lks.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- A-12 Found Buckler's W. Pine bearing tree but R. Pine had been cut and cap broken from pipe.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-12 DNR Monument. 7" W. Pine, S88°W, 10.56' 8" R. Pine, S28°W, 41.2' 10" R. Pine, N56°W, 35.25' 8" Oak, S60°E, 22.5'

GERALD L
WIGGINS
LAND
SURVEYOR
NO.
23521

SIGNED BY Levall & Winggina

DATE 10-10-85

SURVEYOR'S MICHICAN RECISTRATION NO. 23521

(SEAL)