LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LUCE CO.

1 Corner

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	1
1. PUBLIC LAND SURVEY	T. 50 N. R. 8 W.	A-11	
2. PROPERTY CONTROLL- ING IN SECTION—	,T		
3. MISCELLANEOUS PROPERTY IN SECTION —	,T N F. W.		
4. LOT NO , RE	ECORDED PLAT		
5. PRIVATE CLAIMS			,
			REGISTER OF DEEDS STAMP AND FILING NUMBER

- A. Description of original monument and accessories and/or subsequent restoration:
- A-11 S.W. Section Corner of Section 30. Corner set by Billy D. Buckler L. S. on May 28, 1952 from one original B.T. 10" Red Pine, S65°W 22 lks. & 10" Red Pine, S2°E 28 lks.
 - B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- A-11 Replaced pipe and marked new witness as set by Buckler in 1952.
 - C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:DNR Mont.
- A-11 14" R. Pine, \$70°W, 14.52'
 14" R. Pine, \$80°E, 18.48'
 10" R. Pine, \$55°E, 14.2'
 8" W. Pine, \$41°W. 18.2'

Gerald L. Wiggins

SURVEYOR'S MICHIGAN REGISTRATION NO.

DATE 9-10-86

TE 9-10-86

GERALD L
WIGGINS
LAND
UFALISURVEYOR