LAND CORNER RECORDATION CERTIFICATE

	Filing	g Requirement of Act 74, Mich.	. P.A. 1970	
For corners in			1	
Luce	Located In:	Corner Code #		
(County)				
1. Public Land Survey	T50M R T50M R TR			
Property Controlling in Section Miscelleneous Property in Sec.	S TR_ S TR_ S TR_ S TR_		Register of Deeds Stamp & File Num	ber
A Let No	ded Diet			
4. Lot No, Records, Private Claims			ABCDEFGHIJK	Ļ
		Aug 04 1997	2 ├─ ┆ ─ ┼─ ┆─┼─ ┆─┼─ ┆─┼	- -
		Nov 13 1996	3	\bot
L Stephan J. Szyszkoski	, in a field survey on .			-12-
regularments of P.A. 74, Michiga	n P.A. of 1970, the come	r points mentioned in lines 1 and 2 above	re were in	
		d in the current manual of survey instruction anagement or by a decree of a Court of Lar		_ _
		were in conformance with the rules of the i		_[_
Board of Land Surveyors or by	a Decree of a Court of	f Law; established, re-established, monu	umented, '	Ţ
recovered, found as expressed be	IOW:		0 19 20 21 22 23	-24-
NOTE: Not more than 2 comers, all in the same town and range, may be recorded			9	+
on this certificate.	•		10 30 29 28 27 26 +	-2/5
			11	+
			12 31 32 33 34 35	-36-
			13	ᆜ
i7) Corner common to Sections ne 1994 accessories are as fo noted a squared and sc 13) Corner common to Sec. 32- nrcus Schaaf, Reg. Surveyor. Tiver, District Forester. Co	15-16-21-22. Corner llows: 5" J. Pine M69 ribed cedar post adja -33 T50H-RBM and Sec. Maple B.T. (Green) i orner placed and witn	W 4.5', 6' J. Pine H27E 2.7', 6' ocent. - 4-5 T49N-R8M. Corner remonuments n place bearing S20W 25 links. To	the undersigned: found 1" pipe with 4" Brass cap J. Pine SIGE 7.2', 10" J. Pine N74N 85.9' (1952 ted in 1958 by Billy D. Buckler: "Replaced as set free in good condition. Corner shown to us by B. laced a 1" pipe with 4" Brass Cap and made the 56.5 links "S4 MBT".	
B. Description of corner evid	dence found and/or me	whod applied in restoring or reestable	ishing corner:	
thesses. Left the monument accessories as described below [13] Found the 1958 monument, and it record bearingth is a dead stub. The ori	and post in place and . Corner recovered a a 1" I.D. iron pipe ng and distance from ginal Maple 8.T. is n	to facilitate GPS observations, nd rewitnessed by D.Lampela, Membe capped with a 4" dia. brass Michig the remains of the 1958 witnesses:	gan Dept. of Conservation tablet, in good :: The 15° Y. Birch is dead and down, the 16° Y. red. Left the monument in place and marked 4 new	
C. Description of monument 17) found I pipe with 4 Bra azed, scribed, and set seasu 1 the following:	ass cap. (El3 ring nails Blaz	ories established to perpetuate locatin) Found 1° pipe with 4° Brass cap, ed, scribed, and set measuring nai he following:		

7° J. Pine X57N 18.9' "\$16 NBT" 6 Maple S31E 7.7' "S4 MBT" STEPHAN J. 7" J. Pine M28M B.85' "S16 M8T" 14" Hemlock S76W 40.0' "S5 MBT" 10" Maple MOZE 38.05' "S33 MBT" SZYSZKOSKI 11" J. Pine N63E 16.35" "\$15 MBT" 8" J. Pine \$51E 31.15" "\$22 MBT" LAND 10" Maple N40W 25.25" "S32 MBT" Bearings are magnetic. Bearings are magnetic. Signed by

Surveyor's Michigan License No. 33986

For the Michigan Department of Matural Resources - Forest Management Division