			ilrement of Act 7										
For corners in Luce	Located In:		omer Code #										
(County)													
1. Public Land Survey	T <u>50N</u> R T <u>50N</u> R TR	8N_	013 013										
2. Property Controlling in Section	TR S TR S TR S TR	<u> </u>											
3. Miscellaneous Property in Sec.	s tR	<del></del> .				Regis	ter ol	Dee	de St	атр	& FI	Nu	mb
4. Lot No, Reco					1	В	Ç D	E	FG	3 H 1 T	1	J	κ Τ
	D13	Aug 05	1997		2	<u> </u>	╂╌┆	; <del>- </del> -	- <del> </del>	<del>  }</del>	<b>├</b> -	2-	├
		Aug 04			3	-	╂╌┥	+	+			╂	⊬
L Stephan J. Szyszkoski	, in a field survey on		, 19 do he	reby state that under	4	<u></u> ∤-	╀╌┋	-	. b	<u>1</u> '	┿	11	╀╌
regularments of P & 74 Michic	sen P.A. of 1970. the com	er points	mentioned in lines 1 :	and 2 above were it			$\square$	_	-[	$\vdash$		4—	⊢
conformence with regulations an United States Department of the	Interior Ruragy of Land &	Annocem:	int or by a decree of a	Court of Law and /or	6	18-	<b>↓</b> _¹	<del>_</del>	16-	—ı;	<del>-  </del> -	14—	⊢
that the corner noists mentions	d in lines 3, 4 and 5 above	were in a	onformence with the r	ules of the Michigar		$\perp$	$oldsymbol{\sqcup}$		$\perp$	$\vdash \vdash$	-	╄	╄
Board of Land Surveyors or bracovered, found as expressed by	γ a Decree or a Court € selow:	or Law, I	ecebished, 19-96tation	eripa, monumentali	. 8	19_	<u> </u> 2	$\leftarrow$	21_	_2	2	23 <u>—</u>	Ļ
•					9	ot	┷					$\perp$	<u> </u>
NOTE: Not more than 2 co	mers, all in the same 104	AN SANCE FE	nge, may be record	<b>.</b>	10	  30-	<b>⊥</b> ₂l		-28	<u></u> 2	<u>,                                     </u>	 26—	L
Ori una CoralCam.					11		$oxed{oxed{\Box}}$	$\perp$	4	$\sqcup$		$\bot$	$\vdash$
					**		1 1	- 1		1 1	.	J.	1

Description of original monument and accessories and/or subsequent restoration:

(CI3) Corner common to Sections 31-32, T50N-R8M and Sections 5-6 Y49N-R8M. Corner remonumented in 1952 by Dean C. DelaMater as follows: "This corner was pointed out to me by B. McTiver, District Forester, of Newberry. One original B.T. still in place, poor condition. Corner was placed and witnessed May 28, 1952". DelaMater placed a 1" pipe with 4" brass cap at the corner and marked the following: 10" J. Pine N57E II links, 14" R.Pine \$33E 48 links.

(D13) Quarter corner common to Section 32 Y50M-R8W, and Section 5 T49M-R8W. Corner established in 1850 by Wells Burt as follows: "West on South side of Section 32...35.00 Enter level met land...40.00 Set gr. Section post Y. Pine 8 N49E 33, Y. Pine 5 N77W 17. Found no subsequent record.

- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (C13) Found the 1953 monument as described, a 1" I.D. iron pipe capped with a 4" brass Michigan Dept. of Conservation tablet, in good condition, and at record bearing and distance from the remains of the 1952 accessories: the 10° J. Pine is dead but standing, and the 14° R. Pine has been cut. The original B.T. noted above was not recovered. Left the monument in place and marked 4 new mitnesses as described below. Corner recovered and rewitnessed by T. Stark, Newberry District Office.
- (DI3) Original post and accessories not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the corner by single proportionate measurement to the original record between monumented section corners 2658.0' east and west. At the position for the corner, I placed a 1" I.D. x 36" iron pipe capped with a 4" dia. cast aluminum MONR tablet, appropriately stamped. From the corner monumented, the original call for level wet land to the east checks. Corner placed and witnessed by T. Stark, Newberry District office.

C. Description of monument for corner and (CI3) Found i" pipe with 4" brass cap.	accessories established to perpetuate locating the	position of the corner:
lets; round 1 pipe with 4 prass cap. Blazed, scribed, and set measuring hails in the following:	(D13) Set 1° pipe with 4° HDNR cap. Blazed, scribed, and set measuring nails in the following:	AND OF MICHIE
14" R. Pine M60M 38.9' "531 MBT" 14" R. Pine M11E 28.55' "S32 MBT" 12" M. Pine S14M 9.85' "S6 MBT" 12" M. Pine S09E 28.65' "S5 MBT" Bearings are magnetic.	14" M. Pine N18E 12.8' "1/4S NBT" 8" Spruce N30E 17.4' "1/4S NBT" 12" M. Pine S64E 14.7' "1/4S NBT" 16" M. Pine S05E 20.9' "1/4S NBT" 5" squared and scribed M. Pine N30N 32' to center. Bearings are magnetic.	STEPHAN J. SZYSZKOSKI LAND SURVEYOR No. 33986
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

33986 Surveyor's Michigan License No.

For the Michigan Department of Natural Resources - Forest Management Division