

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 50. NR. 9 W.

----- Ince ----- COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sec.'s 32-33 -----

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap -----

WITNESSES TO CORNER 7" Jackpine S 20° E 19 1/2 links -----

8" Jackpine N 70° W 42 links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced corner as perpetuated by Marcus Schaff, Reg. Surveyor.

Found 2" pipe under ground.

Found two B.T.s, yellow pine S 66° W 37 links and yellow pine N 27° W 23 links in good condition.

1/4 corner lies in E-W telephone line and on south edge of road.

Shown to us by B. McTiver, District Forester.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 6/13/57  
REGISTERED LAND SURVEYOR