## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 50 N.R. 9W Luce \_\_\_\_ COUNTY DESCRIPTION OF CORNER &Corner between Sections 35-36 CORMER MONUMENT 1" Pipe with 4" Brass Cap. DATE MONUMENT PLACED AND WITHESSED 7-25-61 557°₩ WITHESSES TO CORNER..... 15" Red Pine (\$\frac{1}{4}S \text{ NBT}) 36 links S69°E  $40\frac{1}{5}$  links 16" Red Pine " " AND

## DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one Pine BT bearing N82°W 15 links. Tree down but in fair condition. Corner lies on W. edge of N-S Fire line.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

Billy D. Buckler

DATE \_\_\_\_\_\_ 30, 1962