

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 50 N.R. 94


Lece COUNTY

DESCRIPTION OF CORNER Section Corner common to Secs. 23-24-25-26

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 7/63

WITNESSES TO CORNER..... 12" Jack Pine (S 26 NBT) S18°W 44 lks.



12" Jack Pine (S25 NBT) South 90 lks.

Corner lies on top of Escarpment

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This Corner was replaced and recorded as set by unknown Surveyor. Found 4" Iron pipe filled with concrete at corner with two Jack pine B.T.s as noted here.

SURVEYOR'S SEAL

*Billy D. Buckler*  
SIGNED BILLY D. BUCKLER DATE 7/30/1964  
REGISTERED LAND SURVEYOR