Cons. 4047 Rev. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 50N N.R. 8-9W

Luce COUNTY

DESCRIPTION OF CORNER ½ Corner bet. Sees, 25-30

CORNER MONUMENT 1" pipe with 4" aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 1-14-70

WITNESSES TO CORNER..... 22" W. Pine (NBT) S 85°E 12.02

N

10" Red Pine (½S NBT) N 22°W 8.97

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line between two section corners.

Found no evidence of original corner here.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

SIGNED Billy D. Buckler DATE 4-17-70

REGISTERED LAND SURVEYOR