

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 50N N. R. 9W


Luce COUNTY

DESCRIPTION OF CORNER West 1/16 corner, Sec. 25

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 1-14-70

WITNESSES TO CORNER..... 12" Jack Pine (BT) N58°W 15.7'



8" Jack Pine (BT) N26°E 13.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed on line and midway between center $\frac{1}{4}$ corner and the west $\frac{1}{4}$ corner.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 4-20-70
REGISTERED LAND SURVEYOR