

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION



# LAND CORNER RECORD

T. 50N N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER South 1/16 Corner Sec. 25

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 3-12-70

WITNESSES TO CORNER..... 10" Red Pine (S 1/16 BT) S9°E 11.6'



10" Jack Pine (S 1/16 BT) S81°W 17.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed on line and midway between center of Section and the south  $\frac{1}{4}$  corner.

SURVEYOR'S SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler DATE 4-20-70  
REGISTERED LAND SURVEYOR