

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 50N N. R. 9W


Luce COUNTY

DESCRIPTION OF CORNER Center Corner, Section 25

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 1-14-70

WITNESSES TO CORNER..... 10" Red Pine (BT) N60°E 4.9'



10" W. Pine (BT) S31°W 5.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed at intersection of straight lines connecting opposite $\frac{1}{4}$ corners; according to rules for sub-division of standard sections.

Corner lies 20' north of road.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 4-14-70