

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 50N N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER North 1/16 Corner, Sec. 25

CORNER MONUMENT 1" pipe with 4" aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 1-14-70

WITNESSES TO CORNER..... 7" Red Pine (N 1/16 BT) N30°W 1.7'



CIRCLE CORNER REGISTERED

8" Jack Pine (BT) S14°W 4.7'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway between the north  $\frac{1}{4}$  corner and the center  $\frac{1}{4}$  corner; according to rules for Sub-division of a standard section.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 4-14-70  
REGISTERED LAND SURVEYOR