LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -: LOCATED IN -:	CORNER CODE NUMBER LIUINGS 70N
1. PUBLIC LAND SURVEY 12 T. 1 N. R. 3 E.	M-5, L-5
2. PROPERTY CONTROLL- ING IN SECTION——,T. —— N. E. W.	
3. MISCELLANEOUS N. E. PROPERTY IN SECTION T. T. S., R. W.	
4. LOT NO , RECORDED PLAT	
5. PRIVATE CLAIMS	REGISTER OF DEEDS STAMP AND FILING NUMBER
I,	
B. Description of corner evidence found and/or method applied M-5 SE Corner Section 12 Found by witnesses by P.L. Benton 1/2" iron rod 12" below surface South-24.68' - sp. Willow stump S65°W-67.40' - sp. 24" Maple stump	d in restoring or re-establishing corner: L-5 S 1/4 Corner Section 12 Found by witnesses by P.L. Benton 3/4" iron pipe 12" below surface South-33.06' - 1/2" rod S10°W-25.08' - Nail in top of post S35°W-35.31' - Nail in top of post
C. Description of monument for corner and accessories establish M-5 SE Corner Section 12 1/2" iron rod 12" below surface South-7.92' - 3/8" iron pipe North-1' - North edge gravel S10°W-32.36'- Fence Post N40°W-32.63' - Fence Post N28°W-32.90' - 12" Apple Tree N71°E-31.34' - 6" Oak	hed to perpetuate locating the position of the corner: L-5 S 1/4 Corner Section 12 3/4" iron pipe 12" below surface N18°E-15.20' - D.N.R. sign post N13°W-14.8' - N. end 12" C.M.P. S41°W-24.9' - steel post @ S. end 12" C.M.P. S05°-25.3' - Face of fence cor. post 2' above ground
SIGNED BY	DATE
SURVEYOR'S MICHIGAN REGISTRATION NO	(SEAL)
FOR STATE AND UNITED STATES AGENCIES:	LE OF MICH
SIGNED BY	DATE BENALUL.
APPROVED AND SIGNED BY	DATE 12-12-18 7