9-

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

| For corners in | |
|--|--|
| LIVINGSTON Located In: Corner Code # | 1996 NOV 14 P 1: 2D |
| 1, Public Land Survey T_IN R_3E | NANCY HAVILAND REGISTER OF DEEDS LIVERGSTON COUNTY, MI. 40843 |
| 2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R | L.S.C.#584m Register of Deeds Stamp & File Number |
| 4. Lot No, Recorded Plat 5. Private Claims | A B C D E F G H I J K L 1 |
| I. DARRELL HUGHES , in a field survey on //-// 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: | 4 7 3 9 10 11 12 5 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 |
| NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. | 9 10-30-29-28-27-26-25- 11 12-31-32-33-34-35-36- |
| A. Description of original monument and accessories and/or subsequent restoration: GLO: 1825 Black Oak 6", South 88-1/2 degrees West, 20 links White Oak 16", North 55 degrees East, 47 links | UNADILLA |
| B. Description of corner evidence found and/or method applied in restoring or reestablishing cor Found 3/4" iron pipe in road box | ner: , |
| *Additional descriptions and historical information on back | of this sheet. |
| C. Description of monument for corner and accessories established to perpetuate locating the position of monument for corner and accessories established to perpetuate locating the position with 1-1/4" X 36" iron pipe, affixed with 2" dia "Livingston Co. Monumentation Corner, P.S. 19834, careful and faithful perpetuation of the position of 010 DEG. 28.77' SET NAIL/TAG E/S 24" HICKORY. 255 DEG. 60.72' SET NAIL/TAG NE/S 18" ASH. 182 DEG. 72.56' SET NAIL/TAG W/S UTILITY POLE. 084 DEG. 135.88' SET NAIL/TAG S/S 24" ASH. | in existing road box brass cap, stamped |
| Signed by | November 11, 1996 W HICH, |
| | 8 / (H) 111 / C |

UNADILLA TOWNSHIP, TIN, R3E

C-9, CORNER COMMON TO SECTIONS 19, 20, 29 AND 30.

FIELD: 7-9-1996 DARRELL D. HUGHES AND ASSOCIATES

Found 3/4" pipe with threaded cap in road box in centerline of Morton Road (M-106), 0.3' below asphalt grade. The Hickory and Ash trees check to centerline trees. Tree and fence row to North. I recommend, to Good for GPS.

1825 Sylvester Sibley, U.S. Deputy Surveyor, "North between 29 and 39, 80.00 chains, set post". P.7

1972 Clifford Smith files Act 74 for MDOT. P.8

1979 Charles Wilson uses corner in survey. P.9

1996 Witness list. P.10