LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

₽o	r corners in	Filing Requi	rement of Act 74, Mich. P.A. 19	70	DEC.	, i
	Livingston (County)	Located In:	Corner Code ##	IVIRGS	ECIST KANC	.
1.	Public Land Survey	T <u>ln</u> R <u>3E</u> T R T R	Y Y	48843	AVIL	FRED
<u>-</u> 2.	Property Controlling	T R S T R		- 3	1 to 6	ź
–ე	in Section Miscellaneous	S T R S T R		L.S.C.# 81m		
- J.	Property in Sec.	S T R		Register of Deeds S	tamp & F	ile Number
		Recorded Plat		— двср	E F G	HIJKLI
-0.	Finale Claims			2 6 5		3
. T	arroll D Hus	[뉴e編 a field survey onDecer	mber 15 93	4 - 7 - 8 -	91	01112
do In I cur Mar abo Cor	hereby certify that under r ines 1 and 2 above were rent manual of survey ins nagement or by a decree ove were in conformance to	equirements of P.A. 74, Michigan P.A. in conformance with regulations at tructions of the United States Depa of a Court of Law and/or that the corn with the rules of the Michigan Board	of 1970, the corner points mentioned and rules therefore as required in the rtment of the Interior, Bureau of Land er points mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of a monumented, recovered, found as	5 6 18 17 7 8 19 20 9 10 30 29	161 212 282	22324
NO	TE: Not more than 4 on this certificate	corners, all in the same town a e.	nd range, may be recorded	11 32 32	333	4 35 36
A.	Description of origina	I monument and accessories an	d/or subsequent restoration:	13		
		k 12" N64E 113 lks. k 14" N48W 355 lks.	•	SUM: PEMONU	S VIV	
					1993	
					#53KC	الم المراد
				Fa. N. () 3 . F . F . ()	Minuel Silve	V I V
3.	Description of corner	al historical informati evidence found and/or method ipe standing 1.0 ft. al	applied in restoring or reestablishi	ng corner:		
		•		,		
	Description of monum	ent for corner and accessories	established to perpetuate locating	the position of the	corner.	
,	I-13, T1N, pipe, affix Monumentatio faithful ree	R3E, UNADILLA, repled with 2" diagon Corner, P.S. 1 stablishment of the 7' SET NAIL/TAG N/S 42' SET NAIL/TAG SV 16' SET NAIL/TAG W/86' FD. 1/2" IRON F	laced existing corner brass cap, stass cap, stassed existing corner by the lace of the original content of the original corner of the lace	r with 1-1/4 tamped "Liv ted as a	" X 38 ingsto	on Co.
ign	ed by Au	ll this	Approved by Liv. Co. Peer	r Group: Nov.	13, . 199	3
•	eyor's Michigan Licens	se No. 19834	•	PADVED BY MICHIGAN STATE BO.	IRD OF LAND SU	IRVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN. 1983

UNADILLA TOWNSHIP, TOWN 1 NORTH, RANGE 3 EAST

I-13, SOUTHWEST CORNER, SECTION 35

Field 10-20-93

Found 3/4" iron pipe standing 1.0' above grade. 74' West of centerline Joslyn Lake Rd. (24 ft. wd. gravel). iron lies at toe of slope and 8'+/- below Rd. grade. Wet ground to West. No occupation lines, except at tree row to East, beginning at East side Joslyn Lake Rd. Yery evident on 1990 SEMCOG Aerial.

Corner first set by Sylvester Sibley around 1825 coming from the East "on the South boundary of Sec. 35...80.00 chains, set post "...at(edge of) prairie."

1922, Grant Dunning, County Surveyor, "Found stone tipped over in soft ground" Survey No. 129. This stone found from Davis witness' (1878), Dunning identified two new witness trees.

1953, Lyle Munsell, "set 3/4" X 3' pipe 72.7' West of centerline Highway...in line of fence to East." Dunning witness trees gone, stumps O.K." (no mention of stone).

To present, Wilson, Garlock, Benton, Boss, Young have used 3/4" pipe. We did not look for stone.

There is no Act 74 recorded for corner.

I-13UN.DOC