LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

1. PUBLIC LAND SURVEY Sec 3 T. 1 N. R. 4 E. H-3, G-3 2. PROPERTY CONTROLL-ING IN SECTION T. S., R. W. 3. MISCELLANEOUS PROPERTY IN SECTION T. S., R. W. 4. LOT NO. RECORDED PLAT 5. PRIVATE CLAIMS RECORDED PLAT RECORDED PLAT REGISTER OF DEEDS STAMP AND FILING NUMBER REGISTER OF D
3. MISCELLANEOUS PROPERTY IN SECTION T. S., R. W. 4. LOT NO. , RECORDED PLAT 5. PRIVATE CLAIMS REGISTER OF DEEDS STAMP AND FILING NUMBER I, Donald L. Bissell , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on April , 19 87, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on
A. LOT NO, RECORDED PLAT
I,
I,
the corner points mentioned in lines 1 and 2 above were, in a field survey on April 1, 19 67, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:
A. Description of original monument and accessories and/or subsequent restoration.
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: H-3 S 1/4 Corner Section 3 Found Axle Shaft G-3 SW Corner Section 3 Found nail in top of fence corner post
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
H-3 S 1/4 Corner Section 3 Set 4" x36" conc. mon. with alum cap. S61°W-28.90' - 10" Cherry S48°W-78.49' - power pole N61°W-11.20'- 6" White Ash S5°W-20.14' - 14" White Oak G-3 SW Corner Section 3 Set 1/2" rod in top of post S75°E-20.33' - Twin 17" Hickory S2°E-37.93' - 5" Hickory S44°W-21.55' - 12" Cherry N22°W-24.57' - 14" Red Oak
SIGNED BYDATE
SURVEYOR'S MICHIGAN REGISTRATION NO (SEAL)
FOR STATE AND UNITED STATES AGENCIES:
SIGNED BY DATE DOWNEY PARPY
APPROVED AND SIGNED BY JOHN HEGISTERED LAND SURVEYOR SIGNED BY SIG